



The Kenilworth Beach Improvement Project Weekly Construction Progress Update – 11/14/2025

1. Work Completed this Week.

- Demolition activities have been fully completed.
- Excavation of all site materials is ongoing and progressing as scheduled.
- Coordination among trades continues, including excavation, concrete work, and helical pier installation.

2. Work Planned for Next Week

- Completion of remaining excavation activities.
- Installation of helical piers

3. Coordination & Issues

- Safety: No incidents or injuries reported
- Delays: No delays to report

4. Coordination & Issues

- Attached for reference



Figure 1: Concrete material to be removed.




Figure 2: south end of the old water treatment plant, generator room removed.



Figure 3: Temporary enclosure of new door entry on the north side of the building.




Figure 4: Area covered and prepared for concrete pour.



Figure 5: Remaining west wall of the generator room.



Figure 6: Grading being done on the bluff for new ramp design.




Figure 7: View of excavation area on the south end of the site.



Figure 8: Abandoned water pipes found under the generator room.



Figure 9: View of the south end of the building facing west.



Figure 10: Additional view of the south side of the building.